

§ 39.13 [Amended]

2. Section 39.13 is amended by adding a new airworthiness directive to read as follows:

AD 99-03-10 Agusta S.p.A.: Amendment 39-11080. Docket No. 99-SW-10-AD.

Applicability: Model A109E helicopters, serial numbers up to and including 11036, certificated in any category.

Note 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must use the authority provided in paragraph (d) to request approval from the FAA. This approval may address either no action, if the current configuration eliminates the unsafe condition, or different actions necessary to address the unsafe condition described in this AD. Such a request should include an assessment of the effect of the changed configuration on the unsafe condition addressed by this AD. In no case does the presence of any modification, alteration, or repair remove any helicopter from the applicability of this AD.

Compliance: Required as indicated, unless accomplished previously.

To prevent loss of the metallic clamp or the engine exhaust ejector which could result in damage to the main or tail rotor system and subsequent loss of control of the helicopter, accomplish the following for each engine:

(a) Prior to further flight, in accordance with Part I of the Compliance Instructions in Agusta Bollettino Tecnico No. 109EP-3, dated December 22, 1998 (Technical Bulletin), inspect the exhaust ejector to ejector saddle locking system, the dampers at the bottom of the ejector saddle, and the torque of the metallic clamp, and install safety wire on the metallic clamp. If any damage is found as a result of the inspection, accomplish Part II of the Compliance Instructions in the Technical Bulletin prior to further flight.

(b) Within the next 10 hours time-in-service (TIS), inspect the dampers and metallic clamps, and reposition and modify the ejector saddle and the locking metallic clamp in accordance with Part II of the Compliance Instructions in the Technical Bulletin.

(c) Thereafter, at intervals not to exceed 25 hours TIS, inspect the metallic clamp, locking mechanism, and dampers in accordance with Part III of the Compliance Instructions in the Technical Bulletin.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Rotorcraft Directorate, Rotorcraft Standards Staff, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Standards Staff.

Note 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Rotorcraft Standards Staff.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) The inspections and modification shall be done in accordance with Agusta Bollettino Tecnico No. 109EP-3, dated December 22, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Agusta S.p.A., 21017 Cascina Costa di Samarate (VA), Via Giovanni Agusta 520, telephone (0331) 229111, fax (0331) 229605-222595. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on April 5, 1999, to all persons except those persons to whom it was made immediately effective by Priority Letter AD 99-03-10, issued January 28, 1999, which contained the requirements of this amendment.

(h) The subject of this AD is addressed in Registro Aeronautico Italiano (Italy) AD No. 98-465, dated December 24, 1998.

Issued in Fort Worth, Texas, on March 10, 1999.

Eric Bries,

Acting Manager, Rotorcraft Directorate, Aircraft Certification Service.

[FR Doc. 99-6556 Filed 3-18-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. 98-CE-78-AD; Amendment 39-11007; AD 99-02-15]

RIN 2120-AA64

Airworthiness Directives; Avions Pierre Robin Model R2160 Airplanes

AGENCY: Federal Aviation Administration, DOT.

ACTION: Direct final rule; confirmation of effective date.

SUMMARY: This action confirms the effective date of Airworthiness Directive (AD) 99-02-15, which applies to certain Avions Pierre Robin Model R2160 airplanes. AD 99-02-15 requires repetitively inspecting the engine bearer for cracks, and replacing the engine bearer with a reinforced part either immediately or at a certain time period depending on whether cracks are found during the inspections. Replacing the engine bearer with a reinforced part terminates the repetitive inspection requirement. This AD is the result of mandatory continuing airworthiness

information (MCAI) issued by the airworthiness authority for France. The actions specified in this AD are intended to detect and correct cracks in the engine bearer, which could result in the engine separating from the airplane.

EFFECTIVE DATE: March 29, 1999.

FOR FURTHER INFORMATION CONTACT: Mr. Karl M. Schletzbaum, Aerospace Engineer, FAA, Small Airplane Directorate, 1201 Walnut, suite 900, Kansas City, Missouri 64106; telephone: (816) 426-6932; facsimile: (816) 426-2169.

SUPPLEMENTARY INFORMATION: The FAA published this direct final rule with request for comments in the **Federal Register** on January 26, 1999 (64 FR 3817). The FAA uses the direct final rulemaking procedure for a non-controversial rule where the FAA anticipates that there will be no adverse public comment. This direct final rule advised the public that no adverse comments were anticipated, and that unless a written adverse comment, or a written notice of intent to submit such an adverse comment, was received within the comment period, the regulation would become effective on March 29, 1999. No adverse comments were received, and thus this notice confirms that this final rule will become effective on that date.

Issued in Kansas City, Missouri, on March 11, 1999.

Marvin R. Nuss,

Acting Manager, Small Airplane Directorate, Aircraft Certification Service.

[FR Doc. 99-6713 Filed 3-18-99; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 71

[Airspace Docket No. 97-ASW-24]

RIN 2120-AA66

Modification to the Gulf of Mexico High Offshore Airspace Area

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: This action amends the Gulf of Mexico High Offshore Airspace Area. Specifically, this action modifies the Gulf of Mexico High Offshore Airspace Area by extending the boundaries further east and south of the current location to the Houston Air Route Traffic Control Center (ARTCC) Flight Information Region/Control Area (FIR/CTA). The FAA is taking this action to